

**WORKOVER PROCEDURE**

**WELL NAME:** WASTE MANAGEMENT USX Y #3-6 **DATE:** 12/12/2013  
**LOCATION:**  
Qtr/Qtr: SENW Section: 3 Township: 2N Range: 64W  
**COUNTY:** WELD STATE: CO API #: 05-123-24791

**ENGINEER:** SETH GORDON 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 906' KB Elevation: 4902  
Surface Cmt: 434 SX GL Elevation: 4892'  
Long St Csg: 4 1/2" 11.6# @ 7186' TD: 7195'  
Long St Cmt: 660 SX PBTD: 7170'  
Long St Date: 7/1/2007

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Niobrara Perforations: 6806' - 6906'  
Perforation Interval (2): Codell Perforations: 7043' - 7055'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" tubing @ 7027' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6756", dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) POOH w/workstring to 1006'. Pump approx 400 sx shoe plug. Cement to surface.
- 7) RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.