

WORKOVER PROCEDURE

WELL NAME: MARTINSON 25-06F **DATE:** 1/15/2014

LOCATION: _____

Qtr/Qtr: SENW Section: 25 Township: 4N Range: 66W
COUNTY: WELD **STATE:** CO **API #:** 05-123-14947

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 508' KB Elevation: 4783'
Surface Cmt: 265 sx GL Elevation: 4772'
Long St Csg: 4 1/2" 11.6# @ 7339' TD: 7360'
Long St Cmt: 400 sx PBTD: 7294'
Long St Date: 3/31/1991

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6940' - 7121'
Perforation Interval (2): Codell Perforations 7237' - 7252'
Perforation Interval (3): _____
Tubing: 2 3/8" tubing @ 7216' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6890', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 4340'. Pump 15 sx balance plug. POOH. If maintain circulation, do not need to tag plug.
- 5) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 660'. Pump approx 250 sx shoe plug. Cement to surface.
- 8) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.