

WORKOVER PROCEDURE

WELL NAME: PEPPLER FEDERAL 01 **DATE:** 1/14/2014

LOCATION: Qtr/Qtr: NESE Section: 22 Township: 4N Range: 66W

COUNTY: WELD STATE: CO API #: 05-123-12499

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 370' KB Elevation: 4744'
Surface Cmt: 210 sx GL Elevation: 4732'
Long St Csg: 4 1/2" 11.6# @ 7361' TD: 7361'
Long St Cmt: 240 sx PBTD: 7311'
Long St Date: 8/18/1985

Plug Back (Sand or CIBP): Sand plug from PBTD to 6648', RBP w/ 2 sx sand @ 6587'
Perforation Interval (1): Niobrara Perforations 6931' - 7131'
Perforation Interval (2): Codell Perforations 7227' - 7255'
Perforation Interval (3): _____
Tubing: 2 3/8" @ 6283' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tubing.
- 3) RIH w/ workstring to ~6577', tag sand. Circulate clean down to RBP (6587')
- 4) Release RBP. POOH.
- 5) RIH w/ workstring to top of sand plug (~6648'). Circulate and clean down to 6900'. POOH
- 6) RU WL. RIH w/CIBP. Set CIBP @ 6880', dump bail 2 sx of cement on top.
- 7) RIH w/ WL, shoot squeeze holes at 4520' and 4370'.
- 8) Set CICR at 4420'. Pump 60 sx through, 10 sx on top. POOH
- 9) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 10) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 11) POOH to 470'. Pump approx 200 sx shoe plug. Cement to surface.
- 12) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
- 13) Cut surface casing off 6'-8' below ground.
- 14) Clean up location. Reclaim location. RDMO.