

WORKOVER PROCEDURE

WELL NAME: MOSER H34-02 **DATE:** 1/21/2014

LOCATION:

COUNTY: Qtr/Qtr: NWNE Section: 34 Township: 3N Range: 65W
WELD STATE: CO API #: 05-123-15448

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 523' KB Elevation: 4835'
Surface Cmt: 310 sx GL Elevation: 4825'
Long St Csg: 2 7/8" 7.9# @ 7369' TD: 7380'
Long St Cmt: 225 sx PBTD: 7363'
Long St Date: 3/1/1992

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7131' - 7144'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1 1/4" tubing @ 7108' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 7081', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off +/- 4550'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 6) Pump 50 sx courtesy plug @ 2500'. POOH to 750'. Pump approx 275 sx shoe plug. Cement to surface.
- 7) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.