

WORKOVER PROCEDURE

WELL NAME: ENZUP 21-41 DATE: 1/20/2014

LOCATION: Qtr/Qtr: NESE Section: 21 Township: 5N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-20039

ENGINEER: SETH GORDON 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 476' KB Elevation: 4649' Surface Cmt: 345 sx GL Elevation: 4639' Long St Csg: 4 1/2" 11.6# @ 7183' TD: 7198' Long St Cmt: 670 sx PBDT: 7149' Long St Date: 12/5/2000

Plug Back (Sand or CIBP): CIBP w/ 2 sx cement set at 6920' Perforation Interval (1): Niobrara Perforations 6707' - 6856' Perforation Interval (2): Codell Perforations 7018' - 7034' Perforation Interval (3): Tubing: 2 3/8" @ 6682' Rods: Pump: Misc.:

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6657', dump bail 2 sx of cement on top.
4) Roll hole, run CBL from CIBP to surface to verify cement top. Original drilling report states production casing cement returns to surface, but CBL not ran to surface.
5) RIH w/ workstring. Pump 50 sx courtesy plug @ 4550'
6) POOH w/workstring to 580'. Pump approx 60 sx shoe plug. Cement to surface.
7) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.