

WORKOVER PROCEDURE

WELL NAME: LORENZ FARMS 22-03B **DATE:** 1/20/2014

LOCATION: Qtr/Qtr: NENW Section: 22 Township: 5N Range: 65W

COUNTY: WELD **STATE:** CO **API #:** 05-123-16607

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 516' KB Elevation: 4635'
Surface Cmt: 370 sx GL Elevation: 4624'
Long St Csg: 2 7/8" 6.5# @ 7127' TD: 7095'
Long St Cmt: 170 sx PBSD: 7082'
Long St Date: 3/5/1993

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6670' - 6867'
Perforation Interval (2): Codell Perforations 6973' - 6985'
Perforation Interval (3): _____
Tubing: 1 1/4" tubing @ 6921' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 1 1/4" tbg and lay down.
 - 3) RU WL. RIH w/CIBP. Set CIBP @ 6620', dump bail 2 sx of cement on top.
 - 4) Unland casing. Cut casing off 4550'. POOH with casing laying down on trailer.
 - 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
 - 6) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 620'. Pump approx 220 sx shoe plug. Cement to surface.
 - 7) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
 - 8) Cut surface casing off 6'-8' below ground.
 - 9) Clean up location. Reclaim location. RDMO.