

## WORKOVER PROCEDURE

**WELL NAME:** LOFLAND 22-42 **DATE:** 1/24/2014  
**LOCATION:**  
Qtr/Qtr: NWSE Section: 22 Township: 5N Range: 65W  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-19227

**ENGINEER:** SETH GORDON 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) Do not start operations until: \_\_\_\_\_  
Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 394' KB Elevation: 4639'  
Surface Cmt: 365 sx GL Elevation: 4629'  
Long St Csg: 4 1/2" 13.5# TD: 7190'  
Long St Cmt: 505 sx PBTD: 7129'  
Long St Date: 10/13/1996

Plug Back (Sand or CIBP): **CIBP @ 6950', 1 sx cement**  
Perforation Interval (1): Niobrara Perforations 6730' - 6870'  
Perforation Interval (2): Codell Perforations 7025' - 7036'  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" J-55 @ 6729' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6680', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 4530'. Pump 30 sx balance plug. POOH
- 5) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/ workstring to 500'. Pump approx 220 sx shoe plug. Cement to surface.
- 8) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.