

WORKOVER PROCEDURE

WELL NAME: SYLVESTER 01 DATE: 1/23/2014

LOCATION: Qtr/Qtr: SWSW Section: 31 Township: 5N Range: 65W
COUNTY: WELD STATE: CO API #: 05-123-12010

ENGINEER: SETH GORDON 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 516' KB Elevation: 4677'
Surface Cmt: 250 sx GL Elevation: 4666'
Long St Csg: 4 1/2" 11.6# @ 7201' TD: 7200
Long St Cmt: 190 sx PBTD: 7121
Long St Date: 10/1/1984

Plug Back (Sand or CIBP): Sand plug from PBTD to 6950', RBP w/ 2 sx sand @ 6913'
Perforation Interval (1): Codell Perforations 7079' - 7109'
Perforation Interval (2):
Perforation Interval (3):
Tubing: None Rods:
Pump:
Misc.:

PRODUCTION STATUS: TA
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) RIH w/ workstring to ~6903', tag sand. Circulate clean down to RBP (6913')
3) Release RBP. POOH.
4) RIH w/ workstring to top of sand plug (~6950'). Circulate and clean down to 7050'. POOH
5) RU WL. RIH w/CIBP. Set CIBP @ 7029', dump bail 2 sx of cement on top.
6) Unland casing. Cut casing off 4400'. POOH with casing laying down on trailer.
7) RIH w/ workstring to pump 110 sx stub plug where csg was pulled. If maintain circulation, do not need to tag
8) POOH w/workstring to 2500'. Pump 50 sx courtesy plug.
9) POOH to 620'. Pump approx 275 sx shoe plug. Cement to surface.
10) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
11) Cut surface casing off 6'-8' below ground.
12) Clean up location. Reclaim location. RDMO.