

WORKOVER PROCEDURE

WELL NAME: SCHOTT B33-11 **DATE:** 2/4/2014

LOCATION: Qtr/Qtr: NESW Section: 33 Township: 5N Range: 64W

COUNTY: WELD **STATE:** CO **API #:** 05-123-19483

ENGINEER: GREG ANDERSON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 365' KB Elevation: 4692
Surface Cmt: 255 sx GL Elevation: 4682
Long St Csg: 3 1/2" 9.20# J-55 @ 7013' TD: 7032
Long St Cmt: 140 sx PBSD: 6946
Long St Date: 11/13/1997

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6592' - 6696'
Perforation Interval (2): Codell Perforations 6861' - 6872'
Perforation Interval (3): _____
Tubing: 2 1/16" tbg @ 6832' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 2 1/16" tbg and lay down.
 - 3) RU WL. RIH w/CIBP. Set CIBP @ 6542', dump bail 2 sx of cement on top.
 - 4) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
 - 5) RIH w/ workstring to pump (100) sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
 - 6) POOH w/workstring to 465'. Pump approx 175 sx shoe plug. Cement to surface.
 - 7) RIH. Tag shoe plug. Add cement if needed.
 - 8) Cut surface casing off 6'-8' below ground.
 - 9) Clean up location. Reclaim location. RDMO.