

WORKOVER PROCEDURE

WELL NAME: SOCO 29-02 DATE: 1/31/2014

LOCATION: Qtr/Qtr: NWNE Section: 29 Township: 5N Range: 65W

COUNTY: STATE: CO API #: 05-123-16151

ENGINEER: SETH GORDON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 527' KB Elevation: 4656'
Surface Cmt: 360 sx GL Elevation: 4643'
Long St Csg: 4 1/2" 11.6# @ 7198' TD: 7197'
Long St Cmt: 250 sx Sussex/125 sx CDL/NIO PBSD: 7152'
Long St Date: 9/27/1992

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Sussex Perforations 4384' - 4404'
Perforation Interval (2): Niobrara Perforations 6716' - 6931'
Perforation Interval (3): Codell Perforations 7031' - 7041'
Tubing: 2 3/8" J-55 @ 4375' Rods: _____
Pump: _____
Misc.: ~700' 2 3/8" tbg at bottom, fish in hole since 1993

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 2 3/8" tbg and lay down.
 - 3) Make bit and scraper run, tag to verify top of fish (~6338')
 - 4) RIH, perf at 6325' and 6125'. Set CICR at 6175'.
 - 5) Pump 85 sx through CICR, unsting, pump 10 sx on top. POOH.
 - 6) RU WL. RIH w/CIBP. Set CIBP @ 4334', dump bail 2 sx of cement on top.
 - 7) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
 - 8) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
 - 9) POOH w/workstring to 630'. Pump approx 225 sx shoe plug. Cement to surface.
 - 10) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
 - 11) Cut surface casing off 6'-8' below ground.
 - 12) Clean up location. Reclaim location. RDMO.