

WORKOVER PROCEDURE

WELL NAME: SCHMIDT 30-14G **DATE:** 2/12/2014

LOCATION: Qtr/Qtr: SESW Section: 30 Township: 4N Range: 66W

COUNTY: STATE: CO API #: 05-123-14939

ENGINEER: GREG ANDERSON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 501' KB Elevation: 4825'
Surface Cmt: 265 sx GL Elevation: 4814'
Long St Csg: 4 1/2" 11.6# @ 7387' TD: 7396'
Long St Cmt: 200 sx Sussex/200 sx C/N PBTD: 7333'
Long St Date: 3/30/1991

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6958' - 7179'
Perforation Interval (2): Codell Perforations 7255' - 7270'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 @ 7243' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6908', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 4610'. Pump 35 sx balance plug. POOH.
- 5) Unland casing. Cut casing off +/- 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 600'. Pump approx 225 sx shoe plug. Cement to surface.
- 8) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.