

WORKOVER PROCEDURE

WELL NAME: HERGERT 17-22 DATE: 2/12/2014

LOCATION: Qtr/Qtr: NWNW Section: 17 Township: 6N Range: 66W

COUNTY: WELD STATE: CO API #: 05-123-22715

ENGINEER: SETH GORDON 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 802' KB Elevation: 4840' Surface Cmt: 560 sx GL Elevation: 4828' Long St Csg: 4 1/2" 11.6# @ 7401' TD: 7401' Long St Cmt: 160 sx PBTD: 7378' Long St Date: 3/8/2005

Plug Back (Sand or CIBP): RBP @ 6903' w/ sand to 6880' Perforation Interval (1): Niobrara Perforations 7038' - 7058' Perforation Interval (2): Codell Perforations 7226' - 7244' Perforation Interval (3): Tubing: Rods: Pump: Misc.: (See attached wireline ticket for accurate perf records)

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank. 2) RIH w/ workstring and retrieving head. Tag sand (~6680') 3) Wash sand, circulate clean to RBP. Release RBP. POOH 4) RU WL. RIH w/CIBP. Set CIBP @ 6988', dump bail 2 sx of cement on top. 5) Unland casing. Cut casing off +/- 5000'. POOH with casing laying down on trailer. 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug. 7) Pump 50 sx Courtesy Plug @ 2500'. POOH w/workstring to 910'. Pump approx 320 sx shoe plug. Cement to surface. 8) WOC 4 hours. RIH. Tag shoe plug. Add cement if needed. 9) Cut surface casing off 6'-8' below ground. 10) Clean up location. Reclaim location. RDMO.