

WORKOVER PROCEDURE

WELL NAME: STATE 36-13E DATE: 10/11/2012

LOCATION: Qtr/Qtr: SWSW Section: 36 Township: 4N Range: 67W

COUNTY: WELD STATE: CO API #: 05-123-15445

ENGINEER: SETH GORDON 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 513' KB Elevation: 4782
Surface Cmt: 360 sx GL Elevation: 4770
Long St Csg: 4 1/2" 11.6# @ 7342' TD: 7378
Long St Cmt: 300 sx PBTD: 7320
Long St Date: 2/3/1992

Plug Back (Sand or CIBP):
Perforation Interval (1): NIOBRARA PERFS 6953' - 7128'
Perforation Interval (2): CODELL PERFS 7255' - 7275'
Perforation Interval (3):
Tubing: 2 3/8" 4.7# J-55 @ 7275' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tubing. And lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6903', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off +/- 5500'. POOH with casing laying down on trailer.
5) RIH w/ workstring to 5500' Pump (100) sx stub plug. If maintain circulation, do not need to tag plug.
6) Pump (50) sx plug @2500'. POOH w/workstring to 615'. Pump approx 275 sx shoe plug. Cement to surface.
6) RIH. Tag shoe plug. Add cement if needed.
7) Cut surface casing off 6'-8' below ground.
8) Clean up location. Reclaim location. RDMO.