

# REENTRY PROCEDURE

WELL NAME: C Watkins 18-03 DATE: 8/30/2013  
 LOCATION: Qtr/Qtr: NWSE Section: 18 Township: 4N Range: 63W  
 COUNTY: WELD STATE: CO API #: 05-123-13611

ENGINEER: Ryan Olson 7 Day Notice Sent: \_\_\_\_\_  
 (Please notify Engineer of any major changes prior to work) Do not start operations until: \_\_\_\_\_  
 Notice Expires: \_\_\_\_\_

OBJECTIVE: Re-enter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# set @ 435' KB Elevation: 4650'  
 Surface Cmt: 325 sks GL Elevation: 4640'  
 Long St Csg: 4 1/2" 15.1# set from 4808'-6874' TD: 6881'  
 Long St Cmt: 230 sks, TOC @ 6025' PBTD: 6811'  
 Long St Date: 10/18/1987  
 Plug Info (1) Set bridge plug @ 6500' w/ 2 sks of cmt on top  
 Plug Info (2) 35 sk cmt plug set 1/2 in and 1/2 out of sur csg  
 Plug Info (3) 10 sk cmt plug set @ surface  
 Plug Info (4)  
 Tubing: \_\_\_\_\_ Rods: \_\_\_\_\_  
 Pump: \_\_\_\_\_  
 Misc.: Base Fox Hills @ 302', Deepest water well @ 922'

WELL STATUS: Well Abandoned 10/20/92  
 COMMENTS: Cut surface casing off 4' below ground level and welded on steel cap

- PROCEDURE:
- 1) Survey and locate abandoned well, mark with stake
  - 2) Excavate to expose top of surface casing
  - 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
  - 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
  - 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
  - 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
  - 7) NU flange adaptor and 5k BOP, test BOP.
  - 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
  - 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging.
  - 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
  - 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
  - 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
  - 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
  - 14) Continue RIH, cleaning out with drilling mud or water to 3000'
  - 15) TOO H with cone bit, drill collars, and 2 7/8" tubing.
  - 16) PU and RIH with mule shoe and 2 7/8" tubing to 3000'.
  - 17) RU cement crew and pump a balanced plug of 100 sks 15.8 ppg Class G "neat" cement
  - 18) POOH to 1072' (150' below deepest water well @ 922')