

WORKOVER PROCEDURE

WELL NAME: LILLI UNIT 14-03 **DATE:** 2/28/2014

LOCATION: Qtr/Qtr: SE/SW Section: 3 Township: 8N Range: 58W

COUNTY: WELD **STATE:** CO **API #:** 05-123-14009

ENGINEER: JONATHAN POMERANTZ
(Please notify Engineer of any major changes prior to work)

7 Day Notice Sent: _____
Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:

Surface Csg:	8 5/8" 24# @ 224'	KB Elevation:	4682'
Surface Cmt:	125 sx	GL Elevation:	4672'
Long St Csg:	4 1/2" 10.5# @ 6388'	TD:	6391'
Long St Cmt:	220 sx	PBTD:	6375'
Long St Date:	7/31/1988		

Plug Back (Sand or CIBP): _____
Perforation Interval (1): D Sand Perforations 6238' - 6252'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 6098' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RIH w/ workstring and retrieving head.
- 4) Run down to RBP (6191'), latch on, POOH w/ RBP.
- 5) RU WL. RIH w/CIBP. Set CIBP @ 6188', dump bail 2 sx of cement on top.
- 6) Perforate @ 5300' and set CICR @ 5250'. Pump 40 sx through CICR and 10 sx above CICR.
- 7) Perforate @ 2500' and set CICR @ 2450'. Pump 90 sx through CICR and 10 sx above CICR.
- 8) Cut casing off 700'. POOH with casing laying down on trailer.
- 9) RIH w/ workstring to pump 325 sx stub/shoe plug where csg was pulled. Cement to surface.
- 10) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 11) Cut surface casing off 6'-8' below ground.
- 12) Clean up location. Reclaim location. RDMO.