

WORKOVER PROCEDURE

WELL NAME: MEL BICKLING 31-22 DATE: 3/4/2014

LOCATION: Qtr/Qtr: NW/NE Section: 22 Township: 6N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-11059

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 264' KB Elevation: 4750' Surface Cmt: 210 sx GL Elevation: 4740' Long St Csg: 4 1/2" 11.6# @ 7678' TD: 7688' Long St Cmt: 250 sx PBTD: 7627' Long St Date: 2/26/1983

Plug Back (Sand or CIBP): Perforation Interval (1): Codell Perforations 7083' - 7098' Perforation Interval (2): Perforation Interval (3): Tubing: 2 3/8" 4.7# J-55 tbg @ 7072' Rods: Pump: Misc.:

PRODUCTION STATUS: COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 7033', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off @ 3880'. POOH with casing laying down on trailer.
5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
6) POOH w/workstring to 560'. Pump approx 200 sx shoe plug. Cement to surface.
7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.