

WORKOVER PROCEDURE

WELL NAME: DINNER 13-33 DATE: 3/10/2014

LOCATION: Qtr/Qtr: SW/SW Section: 13 Township: 6N Range: 65W

COUNTY: WELD STATE: CO API #: 05-123-22370

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 395' KB Elevation: 4711'
Surface Cmt: 180 sx GL Elevation: 4701'
Long St Csg: 4 1/2" 11.6# @ 7182' TD: 7186'
Long St Cmt: 160 sx + 410 sx PBTD: 7163'
Long St Date: 1/19/2005

Plug Back (Sand or CIBP):
Perforation Interval (1): Niobrara Perforations 6664' - 6904'
Perforation Interval (2): Codell Perforations 6986' - 7000'
Perforation Interval (3):
Tubing: 2 3/8" ?# ? tbg @ 6968' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/CIBP. Set CIBP @ 6614', dump bail 2 sx of cement on top.
4) RIH w/ workstring to pump 100 sx balance plug @ 4600'. SI, WOC. RIH to tag plug at approx 3300'.
5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
6) RIH w/ workstring to pump 100 sx balance plug where casing was pulled. If maintain circulation, do not need to tag plug.
7) POOH w/workstring to 510'. Pump approx 175 sx shoe plug. Cement to surface.
8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.