

## WORKOVER PROCEDURE

**WELL NAME:** SINJIN E36-03 **DATE:** 3/5/2014

**LOCATION:** Qtr/Qtr: NE/NW Section: 36 Township: 6N Range: 65W

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-16467

**ENGINEER:** JONATHAN POMERANTZ **7 Day Notice Sent:** \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) **Do not start operations until:** \_\_\_\_\_  
**Notice Expires:** \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** **Surface Csg:** 8 5/8" 24# @ 328' **KB Elevation:** 4656'  
**Surface Cmt:** 300 sx **GL Elevation:** 4647'  
**Long St Csg:** 5 1/2" 17# @ 7066' **TD:** 7085'  
**Long St Cmt:** 150 sx + 250 sx stage **PBTD:** 7026'  
**Long St Date:** 1/18/1993

**Plug Back (Sand or CIBP):**

**Perforation Interval (1):** Parkman Perforations 3558' - 3562' (Cement Squeezed 2/13/2002)

**Perforation Interval (2):** Codell Perforations 6900' - 6914'

**Perforation Interval (3):** \_\_\_\_\_

**Tubing:** 2 7/8" 6.5# J-55 tbg @ 6882' **Rods:** \_\_\_\_\_

**Pump:** \_\_\_\_\_

**Misc.:** \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_

**COMMENTS:** \_\_\_\_\_

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 7/8" tbg and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6850', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to pump 60 sx balance plug @ 3900'. SI, WOC. RIH. Tag balance plug (approx 3400').
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 440'. Pump approx 150 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.