

WORKOVER PROCEDURE

WELL NAME: LATHAM 02-43 **DATE:** 4/8/2014

LOCATION:
Qtr/Qtr: SW/SE Section: 2 Township: 4N Range: 65W
Footages: 661' FSL & 1980' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-15775

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 425' KB Elevation: 4684'
Surface Cmt: 120 sx Lite + 150 sx Reg GL Elevation: 4674'
Long St Csg: 4 1/2" 12.6# @ 7166' TD: 7158'
Long St Cmt: 140 sx Class G PBSD: 7085'
Long St Date: _____

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6720' - 6905'
Perforation Interval (2): Codell Perforations 7002' - 7016'
Perforation Interval (3): _____
Tubing: 2 3/8" ?# ? tbq @ 6984' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbq and lay down.
- 3) RU WL. RIH w/CIBP. Set CIBP @ 6670', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 4600'. Pump 30 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 4200'.
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
- 7) POOH w/workstring to 550'. Pump approx 180 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.