

WORKOVER PROCEDURE

WELL NAME: FARAMIR FARMS 06-32 **DATE:** 4/14/2014
LOCATION:
Qtr/Qtr: NW/SW Section: 6 Township: 3N Range: 64W
Footages: 1880' FSL & 458' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-19254
ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 606' KB Elevation: 4832'
Surface Cmt: 420 sx GL Elevation: 4843'
Long St Csg: 4 1/2" 11.6# @ 7206' TD: 7224'
Long St Cmt: 409 sx PBDT: 7166'
Long St Date: 11/23/1996

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 6798' - 6862'
Perforation Interval (2): Codell Perforations 7061' - 7073'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 6769' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

- PROCEDURE:**
- 1) MIRU Workover rig, pump & tank.
 - 2) POOH w/ 2 3/8" tbg and lay down.
 - 3) RU WL. RIH w/CIBP. Set CIBP @ 6748', dump bail 2 sx of cement on top.
 - 4) RIH w/ workstring to 4800'. Pump 40 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 4270'.
 - 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
 - 6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, do not need to tag plug.
 - 7) POOH w/workstring to 710'. Pump approx 225 sx shoe plug. Cement to surface.
 - 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
 - 9) Cut surface casing off 6'-8' below ground.
 - 10) Clean up location. Reclaim location. RDMO.