

REENTRY PROCEDURE

WELL NAME: Kuhn # 1 DATE: 4/9/2014
LOCATION: Qtr/Qtr: SENE Section: 1 Township: 9N Range: 58W
COUNTY: WELD STATE: CO API #: 05-123-05731

ENGINEER: Ryan Olson 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: Re-enter and re-plug

WELL DATA: Surface Csg: 8 5/8" 24# set @ 145' KB Elevation: ?
Surface Cmt: 100 sks GL Elevation: ?
Long St Csg: UNKNOWN size OH to 6290', NO PROD CSG TD: 6290'
Long St Cmt: PBTD:
Long St Date:
Plug Info (1) 10 sk cmt plug placed @ 145' (btm of sur csg)
Plug Info (2) 5 sk cmt plug placed @ surface
Plug Info (3)
Plug Info (4)
Tubing: Rods:
Pump:
Misc.: Base Fox Hills @ 498', Deepest water well @ 680'

WELL STATUS: Well Abandoned 4/12/65

COMMENTS: unknown hole size, cement calculations based on assumption of 7 7/8" hole

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of 8 5/8" surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld 8 5/8" casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to 8 5/8" casing, one 8 5/8" collar and 8 5/8" starter well head
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing, roll hole clean. Verify top of next cement plug inside of surface casing by tagging.
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 5400'
- 15) TOO H with cone bit, drill collars, and 2 7/8" tubing.
- 16) PU and RIH with mule shoe and 2 7/8" tubing to 5300'.
- 17) RU cement crew and pump a balanced plug of 50 sks 15.8 ppg Class G "neat" cement
- 18) POOH to 3000' and pump balanced plug of 50 sks 15.8 ppg Class G "neat" cement
- 19) POOH to 830' (150' below deepest water well @ 680')
- 20) RU cement crew and pump 308 sks of 15.8ppg Class G "neat" cement bring cement to surface
- 21) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 22) Let cement set over night, verify cement has not settled and is still at surface. RDMO