

## PLUG AND ABANDONMENT PROCEDURE

Dove 22N-13HZ

Step	Description of Work
1	This well only has 9 5/8" surface casing cemented to surface. MI and ensure location is safe for wireline.
2	MIRU WL. RIH 9 5/8" CIBP to 80'. Set CIBP.
3	Instruct wireline contractors to e-mail copies of all job summaries and invoices to <a href="mailto:rscDJVendors@anadarko.com">rscDJVendors@anadarko.com</a> within 24 hrs of the completion of the job.
4	Supervisor submit paper copies of all invoices and reports to Joleen Kramer.
5	Excavation crew to notify One Call to clear excavation area around wellhead.
6	Excavate hole around surface casing enough to allow welder to cut 9 5/8" casing minimum 5' below ground level.
7	Welder cut 9 5/8" casing minimum 5' below ground level.
8	MIRU ready cement mixer. Use 4500 psi compressive strength cement, (NO gravel) fill stubout.
9	Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
10	Properly abandon flowlines per Rule 1103.
11	Back fill hole with fill. Clean location, level.
12	Submit Form 6 to COGCC ensuring to provide 'As performed' WBD identifying operations completed. File electronic Form 42 once abandonment complete.