

Quirk 1

County: Weld
api# 05-123-05175
NESE Sec 19 T5N R61W

Well Notes:

- Step 1.) Contact landowner 48 hours prior to commencing work on this well
- 2.) Contact state representative 48 hours prior to commencing work on this well
- 3.) Locate Dry Hole Marker
- 4.) Build temporary pad and access road for Completion rig and cement unit
- 5.) Cut off Dry hole marker
- 6.) Verify pipe size and weld on wellhead flange and riser
- 7.) MIRU completion rig and NU BOP
- 8.) MU 7 7/8" bit without nozzles and drill collars to drill out surface plug
- 9.) TIH w/ bit, drill collars and 2 7/8" PH6 tubing to next plug
- 10.) Continue to circulate mud to ensure hole clean out
- 11.) Continue TIH to 2500' and circulate two bottoms up (301 bbls)
- 12.) TOOH and LD bit and collars
- 13.) TIH to 2500' w/ 2 7/8" PH6 tubing
- 14.) RU Cementers
- 15.) Pump 50 sx balanced plug
- 16.) TOOH to surface casing shoe
- 17.) Pump 50 sx balanced plug from 183' to 83'
- 18.) RD cementers
- 19.) TOOH and LD tubing
- 20.) RDMO completion rig
- 21.) Dump 50' cement inside and outside surface casing
- 22.) Cut off wellhead and riser to 4' below ground level
- 23.) Weld on dry hole marker
- 24.) Clean location and reclaim