



Exploration and Production
Well P&A Procedure

Revision Date:
5/28/2014

Wellname **GM 33-2**
Location **NWSE 2-7S-96W**
Field **South Grand Valley**
County **Garfield, CO**
API **05-045-07128**
ELEV **5,202'**
Footages **1900 FSL 1860 FEL**

Prepared By: Tony Franzone
office phone: 970-285-9377
cell phone: 970-589-1454

Casing: 9-5/8" 36# - 332-ft
4-1/2" 11.6# and 12.6#, N-80, - 6,271-ft
Current Top of Cement: 3,700-ft CBL (RMWS 4/17/1997)

Purpose: Plug to abandon well

Zone:	All Perforations	
Existing Perforations:	Depth	Holes
	4482 - 4681	20
	4791 - 5116	20
	5347 - 5580	20
	5760 - 6101	20
		80
		total
Proposed Procedure		
<ol style="list-style-type: none"> 1 Notify COGCC 48 hrs prior to start of activity via electronic Form 42 2 Set CIBP + 2 sks cement at 4430' ft in 4-1/2" casing 3 Pressure test 4-1/2" casing, pump cement into leaking area 4 Set CIBP at 430' in 4-1/2" casing, perforate 4-1/2" casing with 3 holes phased 120°, at 380' 5 Place a cement plug to cover 4-1/2" backside from perforations to 50' into 9-5/8", and leaving 100' cement in 4-1/2", with a 30% open hole cement excess 6 Cut off 9-5/8" and 4-1/2" casing to 4-ft below ground level 7 Apply a 50-ft cement plug from surface in 4-1/2" - 9-5/8" annulus 8 Place a 50-ft surface cement plug inside 4-1/2" casing 9 Weld in place dryhole marker 10 Backfill cellar 11 Properly abandon flowlines per Rule 1103. File electronic Form 42 after flowline abandonment is complete 		