

WORKOVER PROCEDURE

WELL NAME: WEEZER G02-32 **DATE:** 8/4/2014

LOCATION:

COUNTY: Qtr/Qtr: SE/SW Section: 3 Township: 4N Range: 65W
WELD STATE: CO API #: 05-123-25721

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: Annular Fill - Fox Hills

WELL DATA: Surface Csg: 8 5/8" 24# @ 1340' KB Elevation: 4687'
Surface Cmt: 792 sx GL Elevation: 4674'
Long St Csg: 4 1/2" 11.6# @ 8248' TD: 8257'
Long St Cmt: 1060 sx PBTD: 8183'
Long St Date: 5/14/2008

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Peforations 7756' - 7888'
Perforation Interval (2): Codell Perforations 8071' - 8085'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7011' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Producing 1 bopd & 40 mcf (8 boepd)

COMMENTS: 140 psi on BH

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) Control well with kill fluid.
- 3) POOH 2 3/8" tubing.
- 4) RIH w/ Bit & Scraper. Tag fill if any. Clean out to PBTD (tally in). TOOH.
- 5) RIH w/RBP. Set RBP @ +/-7706' spot 2 sx of sand on top of RBP. Test RBP 2,000psi. TOOH.
- 6) Bleed off bradenhead, unland casing.
- 7) RIH with 1 1/4" down annulus to TOC (approx. 1943').
- 8) Condition hole.
- 9) Pump 100 sx Class G neat cement w/ gas check (TOC +/-1600').
- 10) Stage pump job to 500 psi to compress cement down into TOC.
- 11) POOH with workstring.
- 12) Re-land casing.
- 13) SI, WOC 4 hours. Run CBL.
- 14) Clean out hole, retrieve RBP at 7706'. POOH.
- 15) RIH with 2 3/8" tubing to 7011'.
- 16) RDMO. RWTP.