

WORKOVER PROCEDURE

WELL NAME: DINNER 06-01 **DATE:** 8/6/2014
LOCATION:
Qtr/Qtr: SW/SW Section: 6 Township: 4N Range: 64W
Footages: 600' FSL & 600' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-10898

ENGINEER: JONATHAN POMERANTZ 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 338' KB Elevation: 4844'
Surface Cmt: 150 sx GL Elevation: 4834'
Long St Csg: 4 1/2" 12.6/11.6# @ 7184' TD: 7215'
Long St Cmt: 225 sx PBDT: 7169'
Long St Date: 12/17/1982

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7072' - 7087'
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 2 3/8" ?# ? tbg @ 7061' Rods: _____
Pump: _____
Misc.: Casing Patch @ 2990' (8/30/2000)

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7022', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4600'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) Pump 50 sx courtesy plug @ 2500'. POOH w/ workstring to 530'. Pump 225 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.