

Document Number:
400655864

Date Received:
08/04/2014

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 100322 Contact Name: EILEEN ROBERTS

Name of Operator: NOBLE ENERGY INC Phone: (303) 228-4330

Address: 1625 BROADWAY STE 2200 Fax: (303) 228-4286

City: DENVER State: CO Zip: 80202 Email: eroberts@nobleenergyinc.com

For "Intent" 24 hour notice required, Name: Rains, Bill Tel: (970) 590-6480

COGCC contact: Email: bill.rains@state.co.us

API Number 05-123-05656-00

Well Name: GOVERNMENT Well Number: 43-14

Location: QtrQtr: SENE Section: 14 Township: 9N Range: 59W Meridian: 6

County: WELD Federal, Indian or State Lease Number: _____

Field Name: WILDCAT Field Number: 99999

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.752644 Longitude: -103.938348

GPS Data:
Date of Measurement: _____ PDOP Reading: _____ GPS Instrument Operator's Name: _____

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems

Other Re-enter well, set plug, PA well w/new cement.

Casing to be pulled: Yes No Estimated Depth: _____

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: See Attached procedure of re-entry and new PA

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24.0	300	200	300	0	

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 50 sks cmt from 6778 ft. to 6500 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 50 sks cmt from 5800 ft. to 5700 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 50 sks cmt from 3000 ft. to 1600 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 480 sks cmt from 855 ft. to 0 ft. Plug Type: OPEN HOLE Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:

Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)

Set _____ sacks half in. half out surface casing from _____ ft. to _____ ft. Plug Tagged:

Set _____ sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

PROCEDURE:

- 1) Survey and locate abandoned well, mark with stake
- 2) Excavate to expose top of surface casing
- 3) Weld 2" collar to top of (unknown size) surface casing cap. Make up to collar, pneumatic drill with non-sparking bit. Drill out cap venting possible trapped gas.
- 4) Once verified that no gas exists beneath top of surface casing plate, cut off surface casing below plate with torch, dress up smooth.
- 5) Butt weld surface casing to dressed cut, bringing threaded end of casing to ground level.
- 6) Make up to surface casing, one collar and starter well head (fitting whatever size surface casing is determined to be)
- 7) NU flange adaptor and 5k BOP, test BOP.
- 8) NU and RIH with 6 7/8" cone bit, PU 2 7/8" drill collar, 2 7/8" 8.7# tubing, and TIW valve
- 9) Drill out first cement plug inside surface casing (assuming there is one), roll hole clean. Verify top of next cement plug inside of surface casing by tagging (assumption).
- 10) If unable to verify isolation of surface casing with tag of cement plug, set RBP inside surface casing
- 11) Once isolation of surface casing is established, either with tagging of surface plug or setting of RBP, pressure test surface casing to 200psi
- 12) After pressure test of surface casing, retrieve RBP or continue drill out of cement plug under surface casing shoe.
- 13) Assume pressure under surface casing shoe, roll hole with kill fluid until well dead, or blow down.
- 14) Continue RIH, cleaning out with drilling mud or water to 6600' (or deepest possible depth, call BLM if depth is not reached)
- 15) TOOH with cone bit, drill collars, and 2 7/8" tubing.
- 16) PU and RIH with mule shoe and 2 7/8" tubing to 6500'.
- 17) RU cement crew and pump a balanced plug of 50 sks 15.8 ppg Class G "neat" cement. Tag balanced plug before proceeding uphole
- 18) POOH to 6200' and pump a balanced plug of 50 sks 15.8 ppg Class G "neat" cement. Tag balanced plug before proceeding uphole
- 19) POOH to 5900' and pump a balanced plug of 50 sks 15.8 ppg Class G "neat" cement. Tag balanced plug before proceeding uphole
- 20) POOH to 3000' and pump a balanced plug of 50 sks 15.8 ppg Class G "neat" cement. Tag balanced plug before proceeding uphole
- 21) POOH to 1600' and pump a balanced plug of 50 sks 15.8 ppg Class G "neat" cement. Tag balanced plug before proceeding uphole
- 22) POOH to 855' (50' below Fox Hills base)
- 23) RU cement crew and pump 480 sxs of 15.8ppg Class G "neat" cement bring cement to surface
*Cement calculation based on an assumed 500' of 10 3/4" surface casing and 9" open hole to 855'
- 24) POOH with 2 7/8" tubing. Wait 4 hrs, and tag TOC. If cement has fallen, top off back to surface
- 25) Let cement set over night, verify cement has not settled and is still at surface. RDMO
- 26) Excavate around wellhead to 8' below grade, cut off surface casing, weld on cap
- 27) Backfill hole and reclaim surface to original conditions

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Eileen Roberts
Title: Regulatory Analyst I Date: 8/4/2014 Email: eroberts@nobleenergyinc.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SUTPHIN, DIRK

Date: 8/13/2014

CONDITIONS OF APPROVAL, IF ANY:

Expiration Date: 2/12/2015

<u>COA Type</u>	<u>Description</u>
	1) As built GPS coordinates will be provided on the form 6, SRA. 2) Operator will submit a Form 42 - Offset Mitigation Completed for the re-plugged well, referencing the API Number of the proposed horizontal well. 3) Operator will submit a Form 4 to report date Final Reclamation will commence. Final reclamation should begin as soon as practicable. 4) Operator will schedule a joint onsite inspection with a COGCC Field Inspector prior to any new disturbance. (This applies if there is no final rec inspection in the well file.)
	Note changes to submitted form. 1) Provide 24 hour notice of MIRU via electronic Form 42. 2) If plugs cannot be set as proposed, minimum plugs are as follows: Plug #1: Set (80 sx) cement plug above the Niobrara top, in the Pierre, below 3900' or between 3400'-1600'. Plug #2: Set (40 sx) cement plug from 800-700. Tag plug or cement to surface. Plug #3: Set 15 sx cement plug from 50' to surface. 3) Submit Form 6 – Subsequent Report of Abandonment within 30 days of plugging in accordance with Rule 311. 4) Submit Form 42(s) - OFFSET MITIGATION COMPLETED, in accordance with DJ Basin Horizontal Offset Policy. 5) Provide well location GPS coordinates on Subsequent Report of Abandonment in accordance with COGCC As-Built Location Policy and Rule 215.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
2157771	SURFACE OWNER CONSENT
400655864	FORM 6 INTENT SUBMITTED
400655952	LOCATION PHOTO
400656037	WELLBORE DIAGRAM
400656038	WELLBORE DIAGRAM

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Engineer	Surface casing is a guess. no info on file. 855 not likely. Put 300 as similar to nearby Govt#1 w/ 287'.	8/13/2014 4:20:23 PM
Permit	Oper. submitted surface access consent.	8/7/2014 10:57:04 AM
Permit	Req'd surface access agreement. Rec. inspection from 7/2003 passed.	3/5/2014 7:20:42 AM

Total: 3 comment(s)