

WORKOVER PROCEDURE

WELL NAME: FAGERBERG 12-10G6 DATE: 9/11/2014

LOCATION: Qtr/Qtr: NW/SE Section: 12 Township: 6N Range: 66W
Footages: 1989 FSL & 1994 FEL

COUNTY: WELD STATE: CO API #: 05-123-18543

ENGINEER: JEREMY GILBERT 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17/20# @ 385' KB Elevation: 4802'
Surface Cmt: 165 sx GL Elevation: 4788'
Long St Csg: 2 7/8" 6.50# @ 7326 TD: 7342'
Long St Cmt: 80 sx PBTD: 7283'
Long St Date: 10/10/1994

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 7208' - 7228'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 1 1/2" 2.76# J-55 @ 7199' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
2) POOH w/ 1 1/2" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 7158', dump bail 2 sx of cement on top.
4) RIH w/ workstring to 5300'. Pump 6 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 5100'.
5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
6) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
7) POOH w/ workstring to 520'. Pump 120 sx shoe plug. Cement to surface.
8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
9) Cut surface casing off 6'-8' below ground.
10) Clean up location. Reclaim location. RDMO.