

WORKOVER PROCEDURE

WELL NAME: GOODHARD 22-01 DATE: 9/17/2014

LOCATION: Qtr/Qtr: NE/SW Section: 22 Township: 3N Range: 65W
Footages: 1980 FSL & 1980 FWL

COUNTY: WELD STATE: CO API #: 05-123-14526

ENGINEER: JEREMY GILBERT 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 510' KB Elevation: 4815'
Surface Cmt: 350 sx GL Elevation: 4805'
Long St Csg: 3 1/2" 9.3# @ 7291' TD: 7291'
Long St Cmt: 225 sx PBTD: 7202'
Long St Date: 1/12/1990

Plug Back (Sand or CIBP):
Perforation Interval (1): Codell Perforations 7100' - 7110'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 1/16" 3.25# @ 6970' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 1/16" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 7050', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
6) POOH w/ workstring to 700'. Pump 260 sx shoe plug. Cement to surface.
7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.