

WORKOVER PROCEDURE

WELL NAME: LORENA 32-28 DATE: 9/17/2014
LOCATION: Qtr/Qtr: SW/NE Section: 28 Township: 1N Range: 64W
Footages: 1980 FNL & 1980 FEL
COUNTY: WELD STATE: CO API #: 05-123-10419

ENGINEER: JEREMY GILBERT 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23# @ 328' KB Elevation: 5120'
Surface Cmt: 200 sx GL Elevation: 5108'
Long St Csg: 4 1/2" 11.6# @ 7842' TD: 7846'
Long St Cmt: 200 sx PBTD: 7841'
Long St Date: 10/9/1981

Plug Back (Sand or CIBP):
Perforation Interval (1): D Sand Perforations 7673' - 7694'
Perforation Interval (2):
Perforation Interval (3):
Tubing: 2 3/8" 4.7# ?tbg @ 7575' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 7623', dump bail 2 sx of cement on top.
4) RIH w/ perf gun. Perforate 4 1/2" casing @ 7100'.
5) RIH w/ CICR. Set CICR @ 7000'. Pump 115 sx through and 40 sx on top.
6) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
7) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
8) POOH w/ workstring to 1400'. Pump 455 sx shoe plug. Cement to surface.
9) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
10) Cut surface casing off 6'-8' below ground.
11) Clean up location. Reclaim location. RDMO.