



Photo 1. View of fill slope with some rill erosion occurring on the western edge of the well pad from the access road facing southward.





Photo 2. Gully that is approximately 2 to 3 feet wide and 1 to 1.5 feet deep eroding the fill slope in southwestern corner of the well pad.





Photo 3. View from southwestern corner of the well pad facing center.



Photo 4. View of sediment deposition on the well pad from the cut slopes along the eastern edge of the well pad.





Photo 5. View of gully in northeastern corner of well pad that has eroded through a diversion berm and is eroding sediment onto the well pad.



Photo 6. View of rill erosion in the cut slope on the northern edge of the well pad.





Photo 7. View of erosion along the access road from the well pad facing downhill and westward.





Photo 8. View of erosion along Road 502 and downstream from the entrance to the access road that appears to be caused from stormwater exiting the well pad.