

Document Number:
400692063

Date Received:
09/21/2014

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CHERYL LIGHT

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461

Address: P O BOX 173779 Fax: (720) 929-7461

City: DENVER State: CO Zip: 80217- Email: CHERYL.LIGHT@ANADARKO.COM

For "Intent" 24 hour notice required, Name: Carlile, Craig Tel: (970) 629-8279

COGCC contact: Email: craig.carlile@state.co.us

API Number 05-123-24253-00

Well Name: PEPPLER Well Number: 4-30

Location: QtrQtr: NWNW Section: 30 Township: 3N Range: 67W Meridian: 6

County: WELD Federal, Indian or State Lease Number: _____

Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.202460 Longitude: -104.940100

GPS Data:
Date of Measurement: 03/01/2007 PDOP Reading: 2.6 GPS Instrument Operator's Name: CHRIS FISHER

Reason for Abandonment: Dry Production for Sub-economic Mechanical Problems
 Other _____

Casing to be pulled: Yes No Estimated Depth: 870

Fish in Hole: Yes No If yes, explain details below

Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below

Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7238	7258			
NIOBRARA	6984	7120			

Total: 2 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	724	550	724	12	VISU
1ST	7+7/8	4+1/2	11.6	7,364	538	7,364	3,470	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 6900 with 30 sacks cmt on top. CIBP #2: Depth 80 with 25 sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 30 sks cmt from 4400 ft. to 4000 ft. Plug Type: CASING Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set 120 sacks half in. half out surface casing from 970 ft. to 520 ft. Plug Tagged:
Set 25 sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____
*Wireline Contractor: _____ *Cementing Contractor: _____
Type of Cement and Additives Used: _____
Flowline/Pipeline has been abandoned per Rule 1103 Yes No *ATTACH JOB SUMMARY

Technical Detail/Comments:

4. Prepare location for base beam equipped rig.
5. Check and record Bradenhead pressure. If Bradenhead valve is not accessible, re-plumb so that valve is above GL.
6. MIRU, kill as necessary using clean fresh water with biocide and circulate. ND WH. NU BOP. Unseat landing jt, LD.
7. Notify cementers to be on call. Provide volumes listed below:
 - 7.1 Niobrara Balanced Plug: 41 cu ft/ 30 sx "G" w/20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time, mixed at 15.8 ppg and 1.38 cuft/sk yield (400' inside 4-1/2" casing).
 - 7.2 SX Balanced Plug: 34 cu ft/ 30 sx class "G" w/ 0.4% CD-32, 0.4% ASA-301 mixed at 15.8 ppg and 1.15 cf/sx (400' inside 4-1/2" casing, no excess).
 - 7.3 Stub Plug: 160 cu ft/ 120 sx Type III CaCl2 cement w/0.25 pps cello flake mixed at 14.8 ppg and 1.33 cf/sx (100' inside 4-1/2" csg, 146' in 9" OH + 20% excess, and 204' in 8-5/8" surface casing).
8. TOOH 2-3/8" OD production tubing. Stand back.
9. MIRU WL. RIH gauge ring for 4-1/2", 11.6#/ft casing to 6980'. POOH.
10. RIH CIBP w/ WL. Set at +/- 6900'. POOH. PT CIBP to 1000 psi for 15 minutes. POOH. RD WL.
11. RIH 2-3/8" tbg while hydrotesting tbg to 3000 psi to 6900'. Tag CIBP and pick up 5'.
12. RU Cementers. Pump Niobrara Balanced Plug: 41 cu ft/ 30 sx "G" w/20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 15.8 ppg and 1.38 cuft/sk yield (400' inside 4-1/2" Casing, no excess) to place cement from 6900' to 6500'.
13. PUH to 6300'. Circulate 100 bbls water containing biocide to clear tubing. PUH to 4400' LD tubing.
14. RU Cementers. Pump SX Balanced Plug: 34 cu ft/ 30 sx class "G" w/ 0.4% CD-32, 0.4% ASA-301 mixed at 15.8 ppg and 1.15 cf/sx (400' inside 4-1/2" casing) to place cement from 4400' to 4000'.
15. PUH to 3800'. Circulate 60 bbls water containing biocide to clear tubing. WOC 4 hours.
16. Tag TOC at or above 4000' w/ 2-3/8" OD tubing. If plug is tagged deeper than 4000' contact engineering. Then, TOOH and LD all but 970' of tbg.
17. RU WL. Shoot off casing at or below 870'. RDMO WL. Circulate water containing biocide to remove any gas.
18. NDBOP, NDTH.
19. Install BOP on casing head with 4-1/2" pipe rams.
20. TOOH with 4-1/2" casing, LD.
21. RIH with 2-3/8" OD tubing to 970'.
22. RU Cementers. Pump 10 bbl SAPP with a minimum of 20 bbl fresh water spacer. Spot Stub Plug: 160 cu ft/ 120 sx Type III CaCl2 cement w/0.25 pps cello flake mixed at 14.8 ppg and 1.33 cf/sx (100' in 4-1/2" prod casing, 146' in 9" OH + 20% excess, and 204' in 8-5/8" surface casing) from 970' to 520'.
23. PUH to 300'. Circulate 10 bbls water containing biocide to clear tubing.
24. TOOH. WOC 4 hrs. Tag Cement. Cement top needs to be above 520'; Proceed assuming TOC is above 520'. Otherwise, call production engineer.
25. MIRU WL. RIH 8-5/8" CIBP to 80'. Set, PT to 1000 psi for 15 min. If tests, RDMO WL and WO rig.
26. Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries and invoices to rscDJVendors@anadarko.com within 24 hrs of the completion of the job.
27. Supervisor submit paper copies of all invoices, logs, and reports to Joleen Kramer.
28. Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
29. Excavate hole around surface casing enough to allow welder to cut 8 5/8" casing minimum 5' below ground level.
30. Welder cut 8 5/8" casing minimum 5' below ground level.
31. MIRU ready cement mixer. Use 4500 psi compressive strength cement, (NO gravel) fill stubout.
32. Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
33. Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
34. Properly abandon flowlines per Rule 1103.
35. Back fill hole with fill. Clean location, level.
36. Submit Form 6 to COGCC ensuring to provide 'As performed' WBD identifying operations completed. File electronic Form 42 once abandonment complete.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: CHERYL LIGHT
 Title: SR. REGULATORY ANALYST Date: 9/21/2014 Email: DJREGULATORY@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 10/3/2014

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 4/2/2015

<u>COA Type</u>	<u>Description</u>
	1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing contact COGCC for plugging modifications. 3) For 970' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 674' or shallower. 4) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete. 5) Please submit gyro survey data with Form 6 (s) Subsequent Report of Abandonment.

Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400692063	FORM 6 INTENT SUBMITTED
400692064	PROPOSED PLUGGING PROCEDURE
400692065	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Well Completion Report dated 5/22/2007.	9/30/2014 2:47:42 PM

Total: 1 comment(s)