



Photo 1. View of erosional channels on the southern edge of the working area of the well pad.



Photo 2. View of erosional channels along the steep edge of the access road near the entrance to the well pad.



Photo 3. View of cobble BMP on the surface of the well pad that appears to be in good condition and is likely effective at de-energizing and filtering stormwater flows exiting the well pad here.



Photo 4. View of erosional gully within the eastern edge of the interim reclamation area.



Photo 5. View of cut slope in western portion of the project area. Slope is largely stabilized with vegetation. Minor rill erosion is occurring. Large puddle appears to be contained and is primarily away from driving surfaces.