

WORKOVER PROCEDURE

WELL NAME: DOMENICO MC33-09 **DATE:** 10/15/2014
LOCATION:
Qtr/Qtr: NE/SE Section: 33 Township: 1N Range: 69W
Footages: 2114 FSL: & 542 FEL
COUNTY: BOULDER **STATE:** CO **API #:** 05-013-06460

ENGINEER: JEREMY GILBERT 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 924' KB Elevation: 5336'
Surface Cmt: 370 sx GL Elevation: 5326'
Long St Csg: 3 1/2" 7.7# @ 8370' TD: 8377'
Long St Cmt: 260 sx PBTD: 8321'
Long St Date: 7/25/1994

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations 7787' - 7964'
Perforation Interval (2): Codell Perforations 8198' - 8210'
Perforation Interval (3): _____
Tubing: 2" 3.25# J-55 tbg @ 8191.5' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7737', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 974'. Pump 385 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.