

**WORKOVER PROCEDURE**

**WELL NAME:** MOSER H34-05 **DATE:** 10/30/2014

**LOCATION:**  
Qtr/Qtr: SW/NW Section: 34 Township: 3N Range: 65W  
Footages: 1320 FNL & 1320 FEL

**COUNTY:** WELD **STATE:** CO **API #:** 05-123-15451

**ENGINEER:** JEREMY GILBERT **7 Day Notice Sent:** \_\_\_\_\_  
(Please notify Engineer of any major changes prior to work) **Do not start operations until:** \_\_\_\_\_  
**Notice Expires:** \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 527' KB Elevation: 4840'  
Surface Cmt: 250 sx GL Elevation: 4830'  
Long St Csg: 2 7/8" 6.5# @ 7309' TD: 7326'  
Long St Cmt: 300 sx PBTD: 7260'  
Long St Date: 12/18/1991

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): Codell Perforations 7149' - 7163'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 1 1/4" 2.33# ?tbg @ 7123' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** \_\_\_\_\_

**PROCEDURE:**

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 1/4" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7099', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/workstring to 2500'. Pump 50 sx Courtesy Plug. SI. WOC. RIH. Tag balance plug at approx. 2335'
- 7) POOH w/ workstring to 792'. Pump 290 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.