

## WORKOVER PROCEDURE

**WELL NAME:** LILLI UNIT 02-11 **DATE:** 12/1/2014  
**LOCATION:**  
Qtr/Qtr: NW/NE Section: 11 Township: 8N Range: 58W  
Footages: 660 FNL & 1980 FEL  
**COUNTY:** WELD **STATE:** CO **API #:** 05-123-13826

**ENGINEER:** JEREMY GILBERT 7 Day Notice Sent: \_\_\_\_\_  
(Please notify Engineer of any major Do not start operations until: \_\_\_\_\_  
changes prior to work) Notice Expires: \_\_\_\_\_

**OBJECTIVE:** P&A

**WELL DATA:** Surface Csg: 8 5/8" 24# @ 185' KB Elevation: 4662'  
Surface Cmt: 150 sx GL Elevation: 4652'  
Long St Csg: 4 1/2" 10.5# @ 6336' TD: 6336'  
Long St Cmt: 190 sx PBTD: 6317'  
Long St Date: 3/26/1988

Plug Back (Sand or CIBP): \_\_\_\_\_  
Perforation Interval (1): D Sand Perforations 6176' - 6186'  
Perforation Interval (2): \_\_\_\_\_  
Perforation Interval (3): \_\_\_\_\_  
Tubing: 2 3/8" 4.7# J-55 tbq @ 5896' Rods: \_\_\_\_\_  
Pump: \_\_\_\_\_  
Misc.: \_\_\_\_\_

**PRODUCTION STATUS:** \_\_\_\_\_  
**COMMENTS:** If rods are still downhole, POOH w/rods before beginning procedure

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbq and lay down.
- 3) RIH w/workstring. Cleanout hole @ 6111' to remove sand plug
- 4) RU WL. RIH. Tag RBP @ 6122', dump bail 2 sx of cement on top.
- 5) RIH w/ perf gun. Perforate 4 1/2" casing @ 5500'.
- 6) RIH w/ CICR. Set CICR @ 5400'. Pump 85 sx of cement through and 20 sx on top.
- 7) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 8) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 9) POOH w/ workstring to 750'. Pump 250 sx shoe plug. Cement to surface.
- 10) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 11) Cut surface casing off 6'-8' below ground.
- 12) Clean up location. Reclaim location. RDMO.