

**FORM**  
**6**  
Rev  
12/05

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
Document Number: 400743445			
Date Received: 12/02/2014			

**WELL ABANDONMENT REPORT**

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.  
A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120 Contact Name: CHERYL LIGHT  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-6461  
 Address: P O BOX 173779 Fax: (720) 929-7461  
 City: DENVER State: CO Zip: 80217- Email: CHERYL.LIGHT@ANADARKO.COM

**For "Intent" 24 hour notice required,** Name: Carlile, Craig Tel: (970) 629-8279  
**COGCC contact:** Email: craig.carlile@state.co.us

API Number 05-123-15865-00 Well Number: H 19-14  
 Well Name: WARDELL  
 Location: QtrQtr: SESW Section: 19 Township: 3N Range: 65W Meridian: 6  
 County: WELD Federal, Indian or State Lease Number: \_\_\_\_\_  
 Field Name: WATTENBERG Field Number: 90750

Notice of Intent to Abandon  Subsequent Report of Abandonment

*Only Complete the Following Background Information for Intent to Abandon*

Latitude: 40.205340 Longitude: -104.708970  
 GPS Data:  
 Date of Measurement: 07/18/2006 PDOP Reading: 4.6 GPS Instrument Operator's Name: Paul Tappy  
 Reason for Abandonment:  Dry  Production for Sub-economic  Mechanical Problems  
 Other \_\_\_\_\_  
 Casing to be pulled:  Yes  No Estimated Depth: 1400  
 Fish in Hole:  Yes  No If yes, explain details below  
 Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
 Details: \_\_\_\_\_

**Current and Previously Abandoned Zones**

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7374	7389			

Total: 1 zone(s)

**Casing History**

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	661	460	661	0	CALC
1ST	7+7/8	2+7/8	6.5	7,537	210	7,537	6,682	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7300 with 25 sacks cmt on top. CIBP #2: Depth 80 with 25 sacks cmt on top.  
 CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
 CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set <u>25</u>	sks cmt from <u>7300</u>	ft. to <u>6240</u>	ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input type="checkbox"/>
Set <u>180</u>	sks cmt from <u>4730</u>	ft. to <u>4330</u>	ft.	Plug Type: <u>CASING</u>	Plug Tagged: <input checked="" type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>
Set _____	sks cmt from _____	ft. to _____	ft.	Plug Type: _____	Plug Tagged: <input type="checkbox"/>

Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
 Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)

Set 450 sacks half in. half out surface casing from 1400 ft. to 460 ft. Plug Tagged:   
 Set 25 sacks at surface  
 Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No  
 Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_  
 \*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_  
 Type of Cement and Additives Used: \_\_\_\_\_  
 Flowline/Pipeline has been abandoned per Rule 1103  Yes  No \*ATTACH JOB SUMMARY

Technical Detail/Comments:

5. MIRU WO rig. Kill well as necessary w/ water containing biocide. ND WH, NU BOP.
6. Unseat and LD landing joint. PU w/ 1.66 OD tbg (2.33#, J-55) to break any sand bridges. Do not exceed the safety tensile load of 29,416 lbs (80% of upset yield strength).
7. TOOH and SB 1.66" OD tbg (223 jts landed at 7,342').
8. MIRU Wireline. PU gauge ring for 2-7/8" csg (2.33#). RIH to +/- 7,310'. POOH and LD gauge ring.
9. PU CIBP for 2-7/8" (2.33#, J-55) csg on wireline and RIH to 7,300'. Set CIBP in the csg at 7,300'. POOH and LD the setting tool. Pressure test to 2,500 psi for 15 min. RDMO Wireline.
10. TIH 1.66" OD tbg and tag CIBP at +/- 7,300' while hydrotesting each joint to +/- 3000 psi and tag CIBP. Pick up 5' from tag.
11. MIRU Cementing Services. Spot 25 sx (+/- 34 cuft) of cmt (Class G w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301, and R-3 to achieve 2:30 pump time) mixed at 15.8 ppg and 1.38 cuft/sk from 7,300' to 6,240'. RDMO Cementing Services.
12. PUH w/ 1.66" OD tbg to +/- 6,000' and circulate tbg clean. POOH and LD the 1.66" OD tbg.
13. MIRU Wireline. PU and RIH on wireline one 1' perf guns (1-11/16", 6 spf, 0.37 EHD, 7" penetration, 60o phasing, 1' net, 6 total holes) to 4,730'. Perf squeeze holes at 4,730' in 2-7/8" prod csg. POOH perf guns. RDMO wireline.
14. MIRU Cementing Services. Establish circulation down the 2-7/8" csg up the surface csg. Pump 5 bbls of fresh water, 20 bbls of metalillicate, and 5 bbls of fresh water followed with 180 sx (+/- 207 cuft) of cmt (Class G w/ 0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301) mixed at 15.8 ppg and 1.15 cuft/sk w/ a wiper plug and displace to 4,330' (+/- 24 bbls). Planned cement is from 4,730' to 4,330' in 9" OH (from caliper, plus 20% excess) & from 4,730' to 4,330' in 2-7/8", 6.5# csg. RDMO Cementing Services. WOC for 4 hrs.
15. MIRU Wireline. PU a jet cutter and RIH to tag TOC at +/- 4,330'. If tag is deeper than 4,330', contact the engineer for possible further cement work.
16. PU to 1,400' and cut the 2-7/8" csg. Cut csg and circulate bottoms up. Continue to circulate to remove any gas in the wellbore. RDMO Wireline.
17. ND BOP and tbg head. NU BOP on the surface csg with 2-7/8" pipe rams. Install 3,000 psi ball valves on the csg head outlets. Install a choke or a choke manifold on one outlet.
18. Unland and PU 2-7/8" csg 5'. NOTE: if pressure test didn't pass in step 9, TOOH 2-7/8" csg and TIH while hydrotesting.
19. MIRU Cementing Services. Pump 10 bbls of SAPP (Sodium Acid Pyrophosphate) followed by 20 bbls of fresh water containing biocide prior to pumping cement through the 2-7/8" csg. Spot 450 sx (+/- 517 cuft) of cmt (Type III w/ cello flake and CaCl2 as deemed necessary) mixed at 14.8 ppg at 1.33 cuft/sk. Planned cement is from 1,400' to 663' in 9" OH (from closest caliper, plus 40% excess), and from 663' to 460' inside 8-5/8", 24# surface csg. PUH to 150' and circulate tbg clean, POOH and SB tbg. RDMO Cementing Services. WOC for 4 hrs.
20. Tag TOC w/ 2-7/8" csg and if TOC is deeper than 461' contact engineer for possible further cement work. TOOH and LD 2-7/8" csg.
21. MIRU wireline. PU CIBP on wireline for 8-5/8" (24#) csg and TIH to +/- 80'. Set CIBP and test to 1000 psi for 15 min. POOH and LD wireline. RDMO wireline.
22. RDMO WO rig.
23. NOTE: Instruct cementing & wireline contractors to email copies of all job logs/job summaries & invoices to rscDJVendors@anadarko.com within 24 hours of the completion of the job.
24. Wellsite supervisor should turn all paper copies of cementing reports/invoices and logs into Joleen Kramer.
25. Have excavation contractor notify One-Call to clear for digging around wellhead and flowline removal.
26. Excavate hole around surface casing enough to allow welder to cut 8-5/8" casing minimum 5' below ground level.
27. Welder cut 8-5/8" casing minimum 5' below ground level.
28. MIRU ready cement mixer. Fill the last 80' inside the 8-5/8" prod. casing until 10' below surface. Use 4,500 psi comp

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: CHERYL LIGHT  
 Title: SR. REGULATORY ANALYST Date: 12/2/2014 Email: DJREGULATORY@ANADARKO.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 12/22/2014

**CONDITIONS OF APPROVAL, IF ANY:** \_\_\_\_\_ Expiration Date: 6/21/2015

<b>COA Type</b>	<b>Description</b>
	<ol style="list-style-type: none"> <li>1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU.</li> <li>2) If unable to pull casing contact COGCC for plugging modifications.</li> <li>3) For 1400' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 611' or shallower.</li> <li>4) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete.</li> <li>5) Please submit gyro survey data with Form 6 (s) Subsequent Report of Abandonment.</li> </ol>

## Attachment Check List

<u>Att Doc Num</u>	<u>Name</u>
400743445	FORM 6 INTENT SUBMITTED
400743448	PROPOSED PLUGGING PROCEDURE
400743449	WELLBORE DIAGRAM

Total Attach: 3 Files

## General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Permit	Well Completion Report dated 6/17/1993.	12/11/2014 11:20:48 AM

Total: 1 comment(s)