

WORKOVER PROCEDURE

WELL NAME: DOME FARM STATE 36-02 DATE: 12/23/2014

LOCATION: Qtr/Qtr: NW/NE Section: 36 Township: 5N Range: 65W
Footages: 630 FNL & 1980 FEL

COUNTY: WELD STATE: CO API #: 05-123-11486

ENGINEER: JOCELYN PERROUX 7 Day Notice Sent:
(Please notify Engineer of any major changes prior to work) Do not start operations until:
Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 505' KB Elevation: 4742'
Surface Cmt: 380 sx GL Elevation: 4730'
Long St Csg: 4 1/2" 11.6# @ 7091' TD: 7096'
Long St Cmt: 225 sx PBTD: 7059'
Long St Date: 11/28/1983

Plug Back (Sand or CIBP):
Perforation Interval (1): Niobrara Perforations 6730' - 6856'
Perforation Interval (2): Codell Perforations 7024' - 7039'
Perforation Interval (3):
Tubing: 2 3/8" 4.7# J-55 tbg @ 6993' Rods:
Pump:
Misc.:

PRODUCTION STATUS:
COMMENTS:

- PROCEDURE:
1) MIRU Workover rig, pump & tank.
2) POOH w/ 2 3/8" tbg and lay down.
3) RU WL. RIH w/ CIBP. Set CIBP @ 6680', dump bail 2 sx of cement on top.
4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
6) POOH w/ workstring to 605'. Pump 250 sx shoe plug. Cement to surface.
7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
8) Cut surface casing off 6'-8' below ground.
9) Clean up location. Reclaim location. RDMO.