

WORKOVER PROCEDURE

WELL NAME: MOSSBERG 30-15H6 **DATE:** 1/13/2015

LOCATION: Qtr/Qtr: SW/SE Section: 30 Township: 5N Range: 66W

Footages: 673' FSL & 2000' FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-18112

ENGINEER: GREG J ANDERSON 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 23 lb set @ 535' KB Elevation: 4900'
Surface Cmt: 335 sx GL Elevation: 4888'
Long St Csg: 3 1/2" 7.7# J-55 set @ 7542' TD: 7555'
Long St Cmt: 185 sx PBTD: 7426'
Long St Date: 4/10/2005

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations: 7051' - 7174'
Perforation Interval (2): Codell Perforations: 7349' - 7358'
Perforation Interval (3): _____
Tubing: 2 1/16" 3.25#, J-55 @ 7322' Rods: _____
Pump: _____
Misc.: Top of cement @ 6514'

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 1/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7001', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 1050' (900' water well within 1 mile). Pump 400 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.