

WORKOVER PROCEDURE

WELL NAME: Herbst 27-05 **DATE:** 1/21/2015
LOCATION:
Qtr/Qtr: SE / SE Section: 27 Township: 5 N Range: 64 W
Footages: 660 FSL & 660 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-12920

ENGINEER: Daryl Kveder 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24 lb/ft @ 322' KB Elevation: 4651
Surface Cmt: 11 GL Elevation: 4640
Long St Csg: 4-1/2" 11# @ 6893' TD: 6905'
Long St Cmt: 230 PBTD: 6828'
Long St Date: 1/7/1986

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations (6510-6524', 6600-6717', 6669-6687')
Perforation Interval (2): Codell Perforations (6782-6795')
Perforation Interval (3): N/A
Tubing: 2-3/8" @ 6766' Rods: _____
Pump: N/A
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6460', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 422'. Pump 175 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.