

WORKOVER PROCEDURE

WELL NAME: Ferguson B24-30 **DATE:** 1/22/2015
LOCATION:
Qtr/Qtr: NE/NE Section: 23 Township: 5N Range: 64W
Footages: 150 FNL: & 165 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-25119

ENGINEER: Daryl Kveder 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8", 24# @ 482' KB Elevation: 16'
Surface Cmt: 482' / 332 sx GL Elevation: 4566'
Long St Csg: 4-1/2", 11.6# M-80 @ 6790' TD: 6810'
Long St Cmt: 6790' / 890 sx PBTD: 6810"
Long St Date: 8/5/2007

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations (6380-6564')
Perforation Interval (2): Codell Perforations (6657-6671')
Perforation Interval (3): _____
Tubing: 2-3/8" 4.70# EUE 8rd (213 Jts) Rods: N/A
Pump: N/A
Misc.: _____

PRODUCTION STATUS: Shut-in
COMMENTS: Regulatory Emissions

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6330', dump bail 2 sx of cement on top.
- 4) RIH w/ perf gun. Perforate 4 1/2" csg @ 590'.
- 5) RIH w/ CICR. Set CICR @ 490'. Pump 185 sx through and 40 sx on top.
- 6) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 7) Cut surface casing off 6'-8' below ground.
- 8) Clean up location. Reclaim location. RDMO.