

WORKOVER PROCEDURE

WELL NAME: KOHLER 21-10G6 DATE: 1/22/2015

LOCATION: Qtr/Qtr: NW/SE Section: 21 Township: 6N Range: 66W

Footages: 1976 FSL & 1987 FEL

COUNTY: WELD STATE: CO API #: 05-123-17627

ENGINEER: GREG J ANDERSON 7 Day Notice Sent: (Please notify Engineer of any major changes prior to work) Do not start operations until: Notice Expires:

OBJECTIVE: P&A

WELL DATA: Surface Csg: 7" 17 lb set @ 418' KB Elevation: 4759' Surface Cmt: 172 sx GL Elevation: 4745' Long St Csg: 4 1/2" 11.6# set @ 7278' TD: 7281' Long St Cmt: 62 sx PBDT: 7186' Long St Date: 10/17/1994

Plug Back (Sand or CIBP): Perforation Interval (1): TEST: Sharon Springs, Niobrara, Ft Hayes Perforations: 6818' - 7133' Perforation Interval (2): Codell Perforations: 7148' - 7165' Perforation Interval (3): TEST: Greenhorn Perforations: 7225' - 7226' Tubing: Rods: Pump: Misc.: Codell producer only. CIBP over Greenhorn @ 7186'-7193'. Nio never treated.

PRODUCTION STATUS: COMMENTS:

- PROCEDURE: 1) MIRU Workover rig, pump & tank. 2) POOH w/ 2 3/8" tbg and lay down. 3) RU WL. RIH w/ CIBP. Set CIBP @ 6768', dump bail 2 sx of cement on top. 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer. 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug. 6) POOH w/ workstring to 518'. Pump 150 sx shoe plug. Cement to surface. 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed. Plug must be 318' or shallower. Provide 10 sx plug at surface. 8) Cut surface casing off 6'-8' below ground. 9) Clean up location. Reclaim location. RDMO.