

Engineer: Heath Pottmeyer

Cell: 740-525-3445

Date: 2/2/2015

**PLUG AND ABANDONMENT PROCEDURE
HSR-FRED MAYER 3-15, API 05-123-17926**

Steps

1. Provide 48 hour notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.). Call Automation Removal Group at least 24 hours prior to rig move. Request they catch and remove plunger, isolate production equipment and remove any automation prior to rig MIRU.
2. MIRU slickline services. Pull bumper spring and tag bottom. RDMO slickline services.
3. Prepare location for base beam equipped rig. Install perimeter fence as needed.
4. Check and record Bradenhead pressure. If Bradenhead valve is not accessible, re-plumb so that valve is above GL.
5. MIRU, kill as necessary using clean fresh water with biocide. NDWH. NUBOP. Unseat landing jt, LD.
6. Notify cementers to be on call. Provide volumes listed below:
 - 6.1 Niobrara plug: 25 sx (35 cu-ft) "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time. Mix at 15.8 ppg and 1.38 cu-ft/sk. Cement volume based on 400' in 4 1/2" casing.
 - 6.2 Sussex suicide: 270 sx (299 cu-ft) "G" w/0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301, mixed at 15.8 ppg and 1.15 cu-ft/sk. Cement volume based on 500' in 4 1/2" casing and 500' in a 10" OH with 20% excess. Caliper on file.
 - 6.3 Foxhills plug: 180 sx (226 cu-ft) Type III w/cello flake and CaCl₂ as necessary, mixed at 14.8 ppg and 1.33 cu-ft/sk. Cement volume based on 100' in 4 1/2" casing, 224' in a 10" OH with 20% excess, and 226' in 8 5/8" casing. Caliper on file.
7. TOOH 2 3/8" and 1.66" tubing landed at 7502'. Stand back 2 3/8" tubing and lay down 1.66" tubing.
8. MIRU WL. RIH gauge ring for 2 7/8" 6.5# casing to 7500'. POOH.
9. PU 2 7/8" 6.5# CIBP and RIH w/WL. Set at +/-7470' to abandon J Sand perms. PU dump bailer, dump bail 1 sx class "G" cement on CIBP. POOH.
10. RIH gauge ring for 4 1/2" 11.6# casing to 6900'. POOH.
11. PU 4 1/2" 11.6# CIBP and RIH w/WL. Set at +/-6820' to abandon Niobrara and Codell perms. PT to 1000 psi. RDMO WL.
12. RIH with 2 3/8" tubing to +/- 6820', tag CIBP and PUH 5'. Hydrotest tubing to 3000 psi while RIH.
13. RU cementers. Pump Niobrara plug: 25 sx (35 cu-ft) "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time. Mix at 15.8 ppg and 1.38 cu-ft/sk. Plug to cover 6420'-6820'.
14. PUH to ~6200'. Reverse circulate with water containing biocide to displace cement and clear tubing.
15. POOH. Stand back 3930' of tubing.
16. RU WL. PU 3 1/8" perf guns with 3 spf, 120 degree phasing, 0.50" EHD and RIH w/WL. Shoot 1' of squeeze holes at 4400' and 3900'. RD WL.

17. PU and RIH w/CICR and 2 3/8" tubing, set CICR at ~3930'. Establish circulation with rig pump using water containing biocide.
18. RU cementers. Precede cement with 5 bbl water containing biocide, 20 bbl sodium metasilicate and another 5 bbl water spacer.
19. Pump Sussex suicide: 270 sx (311 cu-ft) "G" w/0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301, mixed at 15.8 ppg and 1.15 cu-ft/sk to place cement between perms from 4400' to 3900'. Under displace and sting out of CICR to leave 3 bbls (~200') on top of retainer. Cement volume based on 10" OH with 20% excess. Caliper readings across entire interval. RD cementers.
20. PUH to ~3700'. Reverse circulate with water containing biocide to displace cement and clear tubing.
21. P&SB 950', LD remainder.
22. RU WL. Shoot off 4 1/2" casing at or below 850'. RD WL. Circulate casing with water containing biocide to remove any gas.
23. NDBOP, NDTH.
24. Install BOP on casing head with 4 1/2" pipe rams.
25. TOOH 4 1/2" casing, LD.
26. RIH with 2 3/8" tubing to 950' inside 4 1/2" casing.
27. RU cementers. Precede cement with 10 bbl SAPP and a minimum 20 bbl fresh water spacer. Pump Foxhills plug: 180 sx (239 cu-ft) Type III w/ cello flake and CaCl₂ as necessary, mixed at 14.8 ppg and 1.33 cu-ft/sk. Plug to cover 950'-850' in 4 1/2" casing, 850'-626' in 10" OH with 20% excess, and 626'-400' in 8 5/8" casing. Caliper readings across entire interval. RD cementers.
28. PUH to 100' and circulate with water and biocide to displace cement and clear tubing.
29. WOC per cement company recommendation. Tag cement at or above 525'. If not, consult with Evans Engineering.
30. RU WL. RIH 8 5/8" 24# CIBP to 80'. Set and pressure test to 1000 psi for 15 minutes. If tests, RDMO WL and WO rig.
31. Instruct cementing and wireline contractors to email copies of all job logs/jobs summaries to rscDJVendors@anadarko.com within 24 hours of completion of the job.
32. Supervisor is to submit paper copies of all invoices, logs, and reports to Sara Kephart.
33. Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
34. Excavate hole around surface casing enough to allow welder to cut casing minimum 5' below ground level.
35. Welder cut casing minimum 5' below ground level.
36. Fill casing to surface using 4500 psi compressive strength cement, (NO gravel).
37. Spot weld on steel marker plate. Marker should contain Well name, Well number, legal location (1/4 1/4 descriptor) and API number.
38. Obtain GPS location data as per COGCC Rule 215 and send to rscDJVendors@anadarko.com.
39. Properly abandon flowlines per Rule 1103. File electronic Form 42 once abandonment complete.
40. Back fill hole with fill. Clean location, level.