

## WORKOVER PROCEDURE

<b>WELL NAME:</b>	STATE A36-10		<b>DATE:</b>	2/6/2015			
<b>LOCATION:</b>							
Qtr/Qtr:	NW/SE	Section:	36	Township:	6N	Range:	64W
Footages:	1980	FSL	&	1980	FEL		
<b>COUNTY:</b>	WELD		<b>STATE:</b>	CO		<b>API #:</b>	05-123-14791
<b>ENGINEER:</b>	DARYL KVEDER			7 Day Notice Sent:			
	(Please notify Engineer of any major changes prior to work)			Do not start operations until:			
				Notice Expires:			
<b>OBJECTIVE:</b>	P&A						
<b>WELL DATA:</b>							
Surface Csg:	8 5/8" 24# @ 315'				KB Elevation:	4633'	
Surface Cmt:	325 sx				GL Elevation:	4623'	
Long St Csg:	2 7/8" 6.5# @ 6932'				TD:	6960'	
Long St Cmt:	375 sx				PBTD:	6922'	
Long St Date:	10/29/1990						
Plug Back (Sand or CIBP):							
Perforation Interval (1):	Codell Perforations 6794' - 6806'						
Perforation Interval (2):							
Perforation Interval (3):							
Tubing:	1 5/16" 2.33# J-55 tbg @ 6773'				Rods:		
Pump:							
Misc.:							
<b>PRODUCTION STATUS:</b>							
<b>COMMENTS:</b>							

### PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1 5/16" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6744', dump bail 2 sx of cement on top.
- 4) RIH w/workstring to 5220'. Pump 30 sx Balance Plug. SI. WOC. Tag plug @ approx. 4200'
- 5) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 6) POOH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 460'. Pump 185 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.