

WORKOVER PROCEDURE

WELL NAME: STATE A36-16 **DATE:** 2/11/2015

LOCATION:
Qtr/Qtr: SE/SE Section: 36 Township: 5N Range: 64W
Footages: 610 FSL & 660 FEL

COUNTY: WELD **STATE:** CO **API #:** 05-123-14779

ENGINEER: DARYL KVEDER 7 Day Notice Sent: _____
(Please notify Engineer of any major changes prior to work) Do not start operations until: _____
Notice Expires: _____

OBJECTIVE: P&A

WELL DATA:
Surface Csg: 8-5/8" 24# K-55 @ 321' KB Elevation: 4637'
Surface Cmt: Surface to 321' sx GL Elevation: 4647'
Long St Csg: 2-7/8" 6.5# N-80 @ 6930' TD: 6935'
Long St Cmt: 240 sx PBTD: 6900'
Long St Date: 10/18/1990

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Niobrara Perforations (N/A)
Perforation Interval (2): Codell Perforations 6759-6771'
Perforation Interval (3): _____
Tubing: 1.9" 2.76# J-55 @6731.2' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6709', dump bail 2 sx of cement on top.
- 4) RIH w/ workstring to 5135'. Pump 10 sx balance plug. SI, WOC. RIH. Tag balance plug @ approx 5035'
- 5) RIH w/ perf gun. Perforate 2-7/8" csg @ 421' □
- 6) RIH w/ CICR. Set CICR @ 321'. Pump 120 sx through and 10 sx on top. Cement to surface. □
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.