

WORKOVER PROCEDURE

WELL NAME: JIM CREEK 01-29 **DATE:** 2/12/2015
LOCATION:
Qtr/Qtr: SW/SW Section: 29 Township: 2N Range: 64W
Footages: 860' FSL & 660' FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-14428

ENGINEER: Janelle Shable 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8 5/8" 24# @ 802' KB Elevation: 4968
Surface Cmt: 500 sx GL Elevation: 4958
Long St Csg: 4 1/2" 11.6# @ 7810' TD: 7815
Long St Cmt: 300 sx PBTD: 7764
Long St Date: 10/13/1989

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations 7135' - 7145'
Perforation Interval (2): Jsand Performations 7590' - 7632'
Perforation Interval (3): _____
Tubing: 2 3/8" 4.7# J-55 tbg @ 7548' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: Uneconomic to do WBI work and tubing repair - P&A recommended
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2 3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 7540', dump bail 2 sx of cement on top.
- 4) RU WL. RIH w/ CIBP. Set CIBP @ 7085', dump bail 2 sx of cement on top.
- 5) RIH w/ perf gun. Perforate 4 1/2" csg as close as possible to TOC @ ~6800'
- 6) RIH with packer. Set packer @ 6700'. Pump 70 sx cement
- 7) POOH with packer.
- 8) Unland casing. Cut casing off @ 2500'. POOH w/ casing laying down on trailer.
- 9) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 10) POOH w/ workstring to 1081'. Pump 415 sx shoe plug. Cement to surface.
- 11) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 12) Cut surface casing off 6'-8' below ground.
- 13) Clean up location. Reclaim location. RDMO.