

## Wardell 20-45: Plug & Abandonment

Laura Decker – 970-339-1279

[Laura.decker@anadarko.com](mailto:Laura.decker@anadarko.com)

- 1 Provide 48 hour notice to COGCC prior to rig up per request on approved Form 6 (e.g. call field coordinator, submit Form 42, etc.). Call automation removal group at least 24 hours prior to rig move. Request they catch and remove plunger, isolate production equipment, and remove any automation equipment prior to MIRU.
- 2 MIRU slickline. RIH to retrieve production equipment and tag for fill (last cleaned out to 7,336' on 12/16/06). Note tagged depth in OpenWells. **\*\*MIRU pressure bomb services. Pull bumper spring, tag bottom, run pressure bomb survey and obtain pressure gradient survey from surface to 7,241' making gradient stops every 1,000'. Forward pressure bomb results to Evens Engineering. RDMO pressure bomb services.** RDMO slickline.
- 3 Prepare location for base beam equipped rig. Install perimeter fence as needed.
- 4 Check and report surface casing pressure. If surface casing is not accessible at ground level, re-plumb so valve is at ground level. (Note: Bradenhead Pressure: 65 psi instantaneous and produced 20 gallons of condensate during form 17 test on 12/1/14).
- 5 MIRU WO rig. Kill well as necessary with water and biocide. ND wellhead. NU BOP.
- 6 Unland 2.38" tbg (221 total joints landed at 7,225') and TOO H standing back 6,940' of 2.38" tubing. LD extra tubing.
- 7 MIRU wireline. RIH with junk basket/gauge ring (4.5" 11.6#) to 6,990'. POOH. PU and RIH with CIBP (4.5", 11.6#) to set at 6,940' (collars at 6,906' and 6,949'). POOH. RDMO wireline.
- 8 MIRU hydrotester. Hydrotest 2.38" tubing to 3,000 psi while TIH open ended. Tag CIBP set at 6,940'. PUH just above CIBP and circulate all gas out of the hole. Pumping water with biocide, pressure test the CIBP and production casing to 1,000 psi for 15 minutes. **If pressure test passes, proceed to next step; otherwise contact engineering.**
- 9 MIRU cementing services. Establish circulation with water and pump 25 sx Class "G" cement with 20% silica flour, 0.4% CD-32 and 0.4% ASA-301 mixed at 15.8 ppg and 1.38 cuft/sx (cement volumes based on 4.5" 11.6# casing capacity from 6,940' to 6,550'). Displace cement to estimated TOC at 6,550' using approx. 25 bbls water. TOO H and LD 2.38" tubing so EOT at +/- 6,350'. Reverse circulate using approx. 49 bbls water (2 times tubing volume) or until returns are clean.
- 10 TOO H and land EOT at 4,800'. LD extra tubing.
- 11 MIRU cementing services. Establish circulation with water and pump 60 sx Class "G" cement with with 0.4% CD-32 and 0.4% ASA-301 mixed at 15.8 ppg and 1.15 cuft/sx (cement volumes based on 4.5" 11.6# casing capacity from 4,800' to 4,050' with no excess). Displace cement to estimate TOC at 4,050' using 15.5 bbls water. TOO H and stand back 2.38" tubing so EOT at +/- 3,850'. Reverse circulate using approx. 30 bbls water (2 times tubing volume) or until returns are clean. RDMO cementing services. WOC to set up per cementing company recommendation.
- 12 PU and TIH with 2.38" tubing to tag cement plug at +/- 4,050'. If cement is not above 4,050' contact engineer, otherwise proceed to next step.
- 13 TOO H and stand back 1,380' of 2.38" tubing. LD extra tubing.
- 14 RIH and jet cut 4.5" production casing at 1,280'. RDMO wireline. Circulate bottoms up and continue circulating to remove any gas from wellbore.
- 15 ND BOP. Install BOP on surface casing head with 4.5" pipe rams. Install 3,000 psi ball valves on both casing head outlets. Install a choke or choke manifold on one outlet.
- 16 TOO H and LD 1,280' of 4.5" casing.
- 17 TIH with 2.38" tubing open ended to 1,380' (100' inside the 4.5" stub).
- 18 MIRU cementing services. Establish circulation through 2.38" tubing with water and pump 10 bbls SAPP mud flush, 20 bbls fresh water spacer, then balanced stub plug using 340 sx Type III cement with cello flake and CaCl<sub>2</sub> as necessary,

## Wardell 20-45: Plug & Abandonment

mixed at 14.8 ppg and 1.33 cuft/sx (cement volumes based on 100' inside 4.5" 11.6# casing, 587' in 9" hole with 40% excess, and 200' in 8-5/8" 24# surface casing). RDMO cementing services.

- 19 TOO H and LD 2.38" tubing until end of tubing is at +/- 200'. Circulate down tubing and up surface casing/tubing annulus until returns are clean to ensure CIBP can be set in clean surface casing. Finish TOO H and LD 2.38" tubing. WOC to set up per cementing company recommendation.
- 20 PU and TIH with 2.38" tubing to tag cement plug at +/- 590'. If cement is not above 590' contact engineer, otherwise proceed to next step.
- 21 TOO H and LD all 2.38" tubing.
- 22 MIRU wireline. PU and RIH with CIBP (8-5/8", 24#/ft). Set CIBP at 80' and pressure test the CIBP to 1,000 psi for 15 mins. If pressure test fails contact engineering, otherwise proceed to next step.
- 23 RDMO wireline. RDMO WO rig.
- 24 Instruct cementing and wireline contractors to e-mail copies of all job logs/job summaries to [rscDJVendors@anadarko.com](mailto:rscDJVendors@anadarko.com) within 24 hours of completion of job.
- 25 Supervisor submit paper copies of all invoices, logs, and reports to Evens Engineering Specialist.
- 26 Excavation crew to notify One Call to clear excavation area around wellhead and for flowlines.
- 27 Excavate hole around surface casing enough to allow welder to cut casing minimum of 5' below ground level.
- 28 Welder cut casing minimum of 5' below ground level.
- 29 Fill casing to surface using 4,500 psi compressive strength cement (NO GRAVEL).
- 30 Spot weld on steel marker plate. Marker should contain well name, well number, legal location (1/4 1/4 descriptor), and API number.
- 31 Obtain GPS location data as per COGCC Rule 215 and send to [rscDJVendors@anadarko.com](mailto:rscDJVendors@anadarko.com)
- 32 Properly abandon flowline per Rule 1103. File electronic Form 42 once abandonment complete.
- 33 Back fill hole with fill. Clean and level location.
- 34 Submit Form 6 to COGCC ensuring to provide "As Performed" WBD identifying operations completed.