

WORKOVER PROCEDURE

WELL NAME: Kindvall 7-35 **DATE:** 2/18/2015
LOCATION:
Qtr/Qtr: SW/NE Section: 35 Township: 5N Range: 65W
Footages: 1980 FNL & 1980 FEL
COUNTY: WELD **STATE:** CO **API #:** 05-123-12457

ENGINEER: Jocelyn Perroux 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8", 24.00 ppf @ 311' KB Elevation: 4,681.50
Surface Cmt: 125 sx GL Elevation: 4,669.50
Long St Csg: 4-1/2", 11.60 ppf, N-80 @ 7,132' TD: 7,132.00
Long St Cmt: 300 sx PBTD: 7,017.00
Long St Date: 6/3/1985

Plug Back (Sand or CIBP): **Tagged fill at 7,017'**
Perforation Interval (1): Niobrara Perforations 6,702.0' - 6,912.0'
Perforation Interval (2): Codell Perforations 7,010.0' - 7,027.0'
Perforation Interval (3):
Tubing: 2-3/8", 4.70 ppf, J-55 @ 6,976.50' Rods: NA
Pump: NA
Misc.:

PRODUCTION STATUS: PR
COMMENTS:

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 2-3/8" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6,602', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 4,280'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 125 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to pump 50 sx balanced plug at 2,500'. If maintain circulation, no need to tag plug.
- 7) POOH w/ workstring to 560'. Pump 220 sx shoe plug. Cement to surface.
- 8) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 9) Cut surface casing off 6'-8' below ground.
- 10) Clean up location. Reclaim location. RDMO.