

FORM
6Rev
12/05State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

400785441

Date Received:

02/03/2015

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 47120

Contact Name: Cheryl Light

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Phone: (720) 929-6461

Address: P O BOX 173779

Fax: (720) 929-7461

City: DENVER State: CO Zip: 80217-

Email: cheryl.light@anadarko.com

For "Intent" 24 hour notice required,

Name: Carlile, Craig

Tel: (970) 629-8279

COGCC contact:

Email: craig.carlile@state.co.us

API Number 05-123-17926-00

Well Name: HSR-FRED MAYER

Well Number: 3-15

Location: QtrQtr: NENW Section: 15 Township: 3N Range: 67W Meridian: 6

County: WELD

Federal, Indian or State Lease Number:

Field Name: WATTENBERG

Field Number: 90750

☒ Notice of Intent to Abandon☐ Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.230650

Longitude: -104.878730

GPS Data:

Date of Measurement: 09/15/2006

PDOP Reading: 2.3

GPS Instrument Operator's Name: Steve Fisher

Reason for Abandonment: ☐ Dry☒ Production for Sub-economic☐ Mechanical Problems☐ OtherCasing to be pulled: ☒ Yes☐ No

Estimated Depth: 850

Fish in Hole: ☐ Yes☒ No

If yes, explain details below

Wellbore has Uncemented Casing leaks: ☐ Yes☒ No

If yes, explain details below

Details:

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth
CODELL	7109	7119			
J SAND	7548	7584			
NIOBRARA	6913	6915			

Total: 3 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bot	Cement Top	Status
SURF	12+1/4	8+5/8	24	626	440	626	0	VISU
1ST	7+7/8	4+1/2	11.6	7,240	200	7,240	6,106	CBL
S.C. 1.1	3+7/8	2+7/8	6.5	7,829	21	7,829	7,280	CBL

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth 7470 with 1 sacks cmt on top. CIPB #2: Depth 6820 with 25 sacks cmt on top.
CIBP #3: Depth 80 with 25 sacks cmt on top. CIPB #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 25 sks cmt from 6820 ft. to 6420 ft. Plug Type: CASING Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged: ☐

Perforate and squeeze at 4400 ft. with 270 sacks. Leave at least 100 ft. in casing 3930 CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth

(Cast Iron Cement Retainer Depth)

Set 180 sacks half in. half out surface casing from 950 ft. to 525 ft. Plug Tagged: ☒

Set 25 sacks at surface

Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: ☐ Yes ☒ No

Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Plugging Date: _____

*Wireline Contractor: _____ *Cementing Contractor: _____

Type of Cement and Additives Used: _____

Flowline/Pipeline has been abandoned per Rule 1103 ☐ Yes ☐ No *ATTACH JOB SUMMARY

Technical Detail/Comments:

5. MIRU, kill as necessary using clean fresh water with biocide. NDWH. NUBOP. Unseat landing jt, LD.

6. Notify cementers to be on call. Provide volumes listed below:

6.1 Niobrara plug: 25 sx (35 cu-ft) "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time. Mix at 15.8 ppg and 1.38 cu-ft/sk. Cement volume based on 400' in 4 1/2" casing.

6.2 Sussex suicide: 270 sx (299 cu-ft) "G" w/0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301, mixed at 15.8 ppg and 1.15 cu-ft/sk. Cement volume based on 500' in 4 1/2" casing and 500' in a 10" OH with 20% excess. Caliper on file.

6.3 Foxhills plug: 180 sx (226 cu-ft) Type III w/cello flake and CaCl2 as necessary, mixed at 14.8 ppg and 1.33 cu-ft/sk. Cement volume based on 100' in 4 1/2" casing, 224' in a 10" OH with 20% excess, and 226' in 8 5/8" casing. Caliper on file.

7. TOOH 2 3/8" and 1.66" tubing landed at 7502'. Stand back 2 3/8" tubing and lay down 1.66" tubing.

8. MIRU WL. RIH gauge ring for 2 7/8" 6.5# casing to 7500'. POOH.

9. PU 2 7/8" 6.5# CIBP and RIH w/WL. Set at +/-7470' to abandon J Sand perms. PU dump bailer, dump bail 1 sx class "G" cement on CIBP. POOH.

10. RIH gauge ring for 4 1/2" 11.6# casing to 6900'. POOH.

11. PU 4 1/2" 11.6# CIBP and RIH w/WL. Set at +/-6820' to abandon Niobrara and Codell perms. PT to 1000 psi. RDMO WL.

12. RIH with 2 3/8" tubing to +/- 6820', tag CIBP and PUH 5'. Hydrotest tubing to 3000 psi while RIH.

13. RU cementers. Pump Niobrara plug: 25 sx (35 cu-ft) "G" w/ 20% silica flour, 0.4% CD-32, 0.4% ASA-301 and R-3 to achieve 2:30 pump time. Mix at 15.8 ppg and 1.38 cu-ft/sk. Plug to cover 6420'-6820'.

14. PUH to ~6200'. Reverse circulate with water containing biocide to displace cement and clear tubing.

15. POOH. Stand back 3930' of tubing.

16. RU WL. PU 3 1/8" perf guns with 3 spf, 120 degree phasing, 0.50" EHD and RIH w/WL. Shoot 1' of squeeze holes at 4400' and 3900'. RD WL.

17. PU and RIH w/CICR and 2 3/8" tubing, set CICR at ~3930'. Establish circulation with rig pump using water containing biocide.

18. RU cementers. Precede cement with 5 bbl water containing biocide, 20 bbl sodium metasilicate and another 5 bbl water spacer.

19. Pump Sussex suicide: 270 sx (311 cu-ft) "G" w/0.25 pps cello flake, 0.4% CD-32, 0.4% ASA-301, mixed at 15.8 ppg and 1.15 cu-ft/sk to place cement between perms from 4400' to 3900'. Under displace and sting out of CICR to leave 3 bbls (~200') on top of retainer. Cement volume based on 10" OH with 20% excess. Caliper readings across entire interval. RD cementers.

20. PUH to ~3700'. Reverse circulate with water containing biocide to displace cement and clear tubing.

21. P&SB 950', LD remainder.

22. RU WL. Shoot off 4 1/2" casing at or below 850'. RD WL. Circulate casing with water containing biocide to remove any gas.

23. NDBOP, NDTH.

24. Install BOP on casing head with 4 1/2" pipe rams.

25. TOOH 4 1/2" casing, LD.

26. RIH with 2 3/8" tubing to 950' inside 4 1/2" casing.

27. RU cementers. Precede cement with 10 bbl SAPP and a minimum 20 bbl fresh water spacer. Pump Foxhills plug: 180 sx (239 cu-ft) Type III w/ cello flake and CaCl2 as necessary, mixed at 14.8 ppg and 1.33 cu-ft/sk. Plug to cover 950'-850' in 4 1/2" casing, 850'-626' in 10" OH with 20% excess, and 626'-400' in 8 5/8" casing. Caliper readings across entire interval. RD cementers.

28. PUH to 100' and circulate with water and biocide to displace cement and clear tubing.

29. WOC per cement company recommendation. Tag cement at or above 525'. If not, consult with Evans Engineering.

30. RU WL. RIH 8 5/8" 24# CIBP to 80'. Set and pressure test to 1000 psi for 15 minutes. If tests, RDMO WL and WO rig.

31. Instruct cementing and wireline contractors to email copies of all job logs/jobs summaries to rscDJVendors@anadarko.com within 24 hours of completion of the job.

32. Supervisor is to submit paper copies of all invoices, logs, and reports to Sara Kephart.

33. Excavation crew to notify One Call to clear excavation area around w

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Cheryl Light
 Title: Sr. Regulatory Analyst Date: 2/3/2015 Email: cheryl.light@anadarko.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: SCHLAGENHAUF, MARK Date: 3/2/2015

CONDITIONS OF APPROVAL, IF ANY: _____ Expiration Date: 9/1/2015

COA Type

Description

	1) Submit Form 42 electronically to COGCC 48 hours prior to MIRU. 2) If unable to pull casing contact COGCC for plugging modifications. 3) For 950' plug: pump plug and displace, shut-in, WOC 4 hours and tag plug – must be 576' or shallower. 4) Properly abandon flowlines as per Rule 1103. File electronic Form 42 once abandonment complete. 5) Please submit existing gyro survey data with Form 6 (s) Subsequent Report of Abandonment.
--	--

Attachment Check List

Att Doc Num

Name

400785441	FORM 6 INTENT SUBMITTED
400785449	PROPOSED PLUGGING PROCEDURE
400785451	WELLBORE DIAGRAM

Total Attach: 3 Files

General Comments

User Group

Comment

Comment Date

--	--	--

Total: 0 comment(s)