

WORKOVER PROCEDURE

WELL NAME: STATE A36-06 **DATE:** 3/10/2015
LOCATION:
Qtr/Qtr: SE/ NW Section: 36 Township: 6N Range: 64W
Footages: 2032 FNL & 1933 FWL
COUNTY: WELD **STATE:** CO **API #:** 05-123-14744

ENGINEER: DARYL KVEDER 7 Day Notice Sent: _____
(Please notify Engineer of any major Do not start operations until: _____
changes prior to work) Notice Expires: _____

OBJECTIVE: P&A

WELL DATA: Surface Csg: 8-5/8" 24# @ 322' KB Elevation: 4624
Surface Cmt: TOC @ Surface sx GL Elevation: 4614
Long St Csg: 2-7/8" 6.5# N-80 @ 6937' TD: 6940
Long St Cmt: TOC @ 5770' sx PBTD: 6905
Long St Date: 10/7/1990

Plug Back (Sand or CIBP): _____
Perforation Interval (1): Codell Perforations (6783-6796)
Perforation Interval (2): _____
Perforation Interval (3): _____
Tubing: 1.9" 2.75# J-55 @ 6763.77' Rods: _____
Pump: _____
Misc.: _____

PRODUCTION STATUS: _____
COMMENTS: _____

PROCEDURE:

- 1) MIRU Workover rig, pump & tank.
- 2) POOH w/ 1.9" tbg and lay down.
- 3) RU WL. RIH w/ CIBP. Set CIBP @ 6733', dump bail 2 sx of cement on top.
- 4) Unland casing. Cut casing off @ 2500'. POOH with casing laying down on trailer.
- 5) RIH w/ workstring to pump 100 sx stub plug where csg was pulled. If maintain circulation, no need to tag plug.
- 6) POOH w/ workstring to 490'. Pump 240 sx shoe plug. Cement to surface.
- 7) SI, WOC. RIH. Tag shoe plug. Add cement if needed.
- 8) Cut surface casing off 6'-8' below ground.
- 9) Clean up location. Reclaim location. RDMO.